

Q4T#
70657

11 SEP 70 21 47

S E C R E T CITE NPIC 9278.

1. IMAGE QUALITY: RANGES FROM POOR TO GOOD WITH MOST IN POOR TO FAIR CATEGORY. POOR IMAGE QUALITY PRIMARILY DUE TO POOR WEATHER CONDITIONS. ONLY A SMALL PORTION OF IMAGERY MAINTAINS SHARPNESS AT MAGS ABOVE 20X. UNSHARP IMAGERY PARTIALLY ATTRIBUTED TO PROBABLE MALFUNCTION IN V/H SENSOR. INDICATIONS THAT MALFUNCTION OCCURRED ARE: V/H METER READS LOWER THAN NORMAL (7.5 TO 8.5 COMPARED TO NORMAL 8.8 TO 9.0), CONJUGATE STEREO IMAGERY SEPARATED BY 3 FRS COMPARED TO USUAL 5 FRS, AND NO OVERLAP BETWEEN SUCCESSIVE FWD OR SUCCESSIVE AFT FRS. RECHECK OF MSN G-126, WHICH UTILIZED SAME CAMERA UNIT, INDICATES SAME PROBLEM. INTERP SUIT IS GENERALLY FAIR. CLOUDS OBSCURE 45 PCT ENTIRE MSN.

A. G-127, 7 SEP 70
B. I-2, 8007
C. A/C 339
D. STEREO
E. T/O: 1102Z, C/ON: 1254Z
F. 3404
G. MX819-1, NRTSC
H. AVG GAMMA: 1.55
I. SLIT: 0.085 IN.
J. FILTER: W-23A

A. EXPOSURE: ADEQUATE.
B. DENSITY: MED; CONTRAST: MED.

NOTED. 5. PHYSICAL DEGRADATION: SIX HEAT AND ONE ULTRASONIC S

E. DATA RECORD EQUIP: FUNCTIONED PROPERLY.

F. OTHER: LAST TITLED FR 1154, COUNTER 1159. BIAS
CONSTANT THROUGHOUT MSN.

4. POSITIVES: ADEQUATE FOR INTERPRETATION.

END OF MESSAGE

DISTRIBUTION		
CY	OFFICE	PI
1	FILE	
2	CABLE SEC.	
	FP&B/RD	
	SECUR.	
3	TSSG	APSD
	PSG/OC	
	RFD	
	REPRO	
	AID	
	IEG	
	IEG/OD	
	SECEN	
	IMAGE WEST	
	SITY MARK	
	PRESENT	
	M&S	
	IEG/PHD	
	PLACES	
	DIA-XX4	
	SPAD	
	DISREP	
	CEE	

25X1

ADVANCE CY
SANITIZED
WITH TEXT

SECRET